



## **ADVICE FOR HAND CLEANING SPLASHBACK GLASS**

### **ROUTINE CLEANING**

Hand cleaning of the coated surface, to visibly remove accumulated dust or fingerprints, can be accomplished using a number of different glass cleaning products.

### **RECOMMENDED ROUTINE CLEANING PRODUCTS**

Windex® Multi-Surface Cleaner (colourless liquid) produced by SC Johnson & Son Pty.Ltd.

A mixture of one part vinegar with ten parts water.

The use of ammonia-based and alcohol-based glass cleaners is not recommended as these products tend to leave visible streaks.

### **ROUTINE CLEANING PROCEDURE**

- It is recommended that jewellery and watches be removed prior to cleaning and that gloves be worn.
- Flood the glass surface with the spray-on cleaning solution or with a cloth saturated with the cleaning solution. Be generous with the amount of solution applied.
- Rub the wet surface with a clean, lint-free towel or cloth.
- Wipe dry with a dry, clean, lint-free towel or cloth. Do not use a squeegee on the glass surface.
- To prevent streaking, stop wiping when the glass is almost dry and there is a uniform film of moisture left on the glass surface. The film will quickly evaporate leaving a clean surface.

### **SPOT CLEANING**

Occasionally spot cleaning may be required to remove stubborn dirt or foreign materials which adhere to the surface such as grease or oil.

**Do not use razor blades, steel wool, scouring bristles or other metallic or abrasive objects on the surface, as this will permanently scratch the product and could void the warranty.**

### **SPOT CLEANING PROCEDURE**

- Apply a small quantity of the cleaner listed above to a clean, wet cloth or towel.
- Rub on areas of glass needing spot cleaning.
- Wipe clean using a dry, clean, lint-free towel or cloth followed by a routine cleaning procedure.

This information is offered as a general guide only. This guidance does not preclude the use of other methods, materials or equipment; however the user should undertake careful evaluation and make suitable enquiries as to the suitability of alternative methods, materials or equipment, before using them. All reasonable care has been taken in producing this document, however The Edge Glass (Aust) makes no representations or warranties, express or implied, as to the accuracy, reliability or completeness of, and disclaims all liability, direct or indirect and whether or not arising out of the negligence, default or lack of care of The Edge Glass (Aust) for any loss or damage (whether foreseeable or not) suffered by the recipient or any other person arising out of, or in connection with, any use of reliance by any of them on this document. Liability which cannot legally be excluded is limited to the maximum extent possible.